


OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT
Tillamook County Surveyor's Office

SECTIONS: 1, 6, 7, 12	TOWNSHIP: 6 South	RANGE: 9 W and 10 W
COUNTY: Tillamook		DATE: 4-26-17
CORNER DESIGNATION: The Section Corner common to Sections 1 and 12, T6S, R10W And Sections 6 and 7, T 6 S, R 9 W, W.M.		(Please check one)
		<input type="checkbox"/> Condition Report Only
		<input type="checkbox"/> Restoration
		<input checked="" type="checkbox"/> Rewitness set 3 new BT's
		<input type="checkbox"/> Unrecorded
		<input type="checkbox"/> Reset at surface
Previous Rewitnesses, Restorations and Surveys, etc. CURRENT MONUMENT SET BY PROCHNAU, B-1112 INDEX FILE E-1 (Rewitness Card # 965) , Book 2, Page 263 B-1111, B-1112, RW 965		
Found Monument(s) and Accessories (Condition & Source): FOUND 2" ALUMINUM PIPE WITH 3-1/4" USFS ALUMINUM CAP UP 12" ON NE SLOPE. 48" D.FIR 15 FT. HIGH STUMP N 74°E (N 77°E) 126.7 FT (124') WITH TAG. SE AND SW FIR BT'S ARE WINDFALLS		
Monument Set (Procedures and Description): NONE	Pictures of Found Monuments: USDA T 6 S R 10 W R 9 W S 1 S 6 + S 12 S 7 1983	
New accessories set:		
New Bearing Trees set: 7" Hemlock S 21°E 33.1 ft. scribed "T6SR9WS7" above "BT". 12" D.Fir N 51°E 36.1 ft. scribed "T6SR9WS6" above "BT". 13" Hemlock S 6°W 25.3 ft. scribed "T6SR10WS12" above "BT".		
Location & Comments: orange post riser, about 75' West of N-S creek and about 130' West of the edge of a Clearcut.		
Firm / Agency Address: NORTHSTAR SURVEYING, INC 720 NW 4 TH ST. CORVALLIS, OR 97330 BCOOK@NORTHSTARSURVEYING.COM		SURVEYOR'S SEAL 
Party Chief: DAN JONES		
Notes:		
Witnesses MARK GANDY		

