



Trask River Road: Culvert 918

This grant request is for construction funding to remove failing AOP Barrier where Hatchery Creek crosses Trask River Road. Designs are fully funded.

The riparian areas surrounding Hatchery Creek below the problem culvert are completely intact with mature trees and a variety of native shrubs. This downstream habitat is an excellent example of what the entire creek system could have the potential to look like if the problem culvert were removed and native plants and trees re-established in the area.

Salmon SuperHwy has been very successful in removing barriers in the Tillamook and Nestucca Watersheds.

